

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	8	("1808792" "2980390" "3411706" "3510230").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/09/05 16:27
L2	2	("3390926").PN.	USPAT; USOCR	OR	OFF	2006/09/05 16:27
S1	1	"5193989".pn.	USPAT	OR	OFF	2006/08/31 15:57
S2	564	(417/403).CCLS.	USPAT; USOCR	OR	OFF	2006/08/31 15:59
S3	4444	turbocharger	USPAT	OR	OFF	2006/08/31 16:00
S4	757	S3 and "turbine wheel"	USPAT	OR	OFF	2006/09/01 10:01
S5	124	S4 and "threaded"	USPAT	OR	OFF	2006/08/31 16:02
S6	1	"6928816".pn. and welding	USPAT	OR	OFF	2006/09/01 09:53
S7	1	"6928816".pn. and weld	USPAT	OR	OFF	2006/09/01 10:01
S8	4444	turbocharger	USPAT	OR	OFF	2006/09/01 10:01
S9	757	S8 and "turbine wheel"	USPAT	OR	OFF	2006/09/01 10:01
S10	5	S9 and "inertia welding"	USPAT	OR	OFF	2006/09/01 10:03
S11	9	("1665458" "2967486" "3914067" "4125344" "4340317" "4538969" "4872817").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/09/01 13:18
S12	48	("1912408" "2010525" "2438866" "2577134" "2602683" "2633804" "2695131" "2722101" "2750892" "2795371" "2839006" "2912155" "2945619" "3037458" "3232043" "3421201" "3451343" "3510230" "3571906" "3676014" "3890780" "3914067" "3961867" "4039268" "4074946" "4095856" "4147468" "4279576" "4296934").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/09/01 13:20
S13	4444	turbocharger	USPAT	OR	OFF	2006/09/01 13:26
S14	757	S13 and "turbine wheel"	USPAT	OR	OFF	2006/09/01 13:29
S15	757	S13 and "turbine wheel"	USPAT; USOCR	OR	OFF	2006/09/01 13:36
S16	1	"6896479".pn. and bearing	USPAT; USOCR	OR	OFF	2006/09/01 14:44
S17	6	S13 and "inertia welding"	USPAT; USOCR	OR	OFF	2006/09/01 14:44
S18	1	S13 and "inertia weld"	USPAT; USOCR	OR	OFF	2006/09/01 14:44

EAST Search History

S19	4	S13 and "inertia welded"	USPAT; USOCR	OR	OFF	2006/09/01 14:55
S20	3	S13 and "male threads"	USPAT; USOCR	OR	OFF	2006/09/01 14:47
S21	6293	"turbine wheel"	USPAT; USOCR	OR	OFF	2006/09/01 14:51
S22	10	S21 and "inertia welding"	USPAT; USOCR	OR	OFF	2006/09/01 14:53
S23	54	S21 and (threads with turbine)	USPAT; USOCR	OR	OFF	2006/09/01 14:53
S24	4	method with "turbocharger assembly"	USPAT	OR	OFF	2006/09/05 14:52